FPN = E0950



Location:
1640 Norwood AVE
Itasca IL 60143

Incident Type:

410 - Combustible/flammable gas/liquid condition, other

Zone:

District 06 - Itasca (Roselle Fire Protection District)

Location Type: 1 - Street address

FDID: DD321

Incident #: 2008-1905 Exposure ID: 1082571

Exposure #: 0

Incident Date: 10/18/2008

Roselle Fire Department

Station: 1 Shifts Or Platoon: 1 Black

Report Completed by:	ID: 1046	Name: Gnadt, David	Date: 10/18/2008
Report Reviewed by:	ID: 1005	Name: Auble, Marcus	Date: 10/20/2008
Report Printed by:	ID: 1005	Name: Auble, Marcus	Date: 10/20/2008 Time: 7:32:04 AM

Structure Type:	Property Use: 9	40 - Water	area, c	ther			
Automatic Exting	uishment System I	Present: 🗌	Detecto	ors Pr	esent: 🗆	Cause of Ignition:	
Aid Given or Rece	other aid given	Primary	action ta	ken:	42 - Ha	Mat detection, monitoring, sampl	ing, & analysis
Additional actions	: 43 - Hazardo	us materia	ls spill	cont	rol and c	onfinement, 82 - Notify other age	ncies.
Property Losses:		vilian Injurie				Fire Service Injuries:	0
Contents Losses:	Ci	vilian Fatalit	ies:		0	Fire Service Fatalities:	0
Total Losses:	To	otal Casualiti	es:		0	Total Fire Service Casualties:	0
Total # of appara	tus on call:			5	Total #	of personnel on call:	16

NARRATIVE

Engine 521, Squad 541 and Medic 532 respond Still Alarm for the outside odor investigation. On arrival, Itasca Police on scene and stated several occupants from apartment complex smelled odor from pond located south of complex. Companies investigated, starting at the west end of pond. Slight film of fuel noted around pond's edges and odor of fuel stronger as companies investigated east. Companies found fuel coming from sewer drain at east end of pond near 1640 Norwood Av.

Alarm upgraded to Full Still and Deputy Chief Metoyer requested to scene. Companies utilized absorbent "booms" to contain fuel. Itasca water department, EPA and Glenside Hazardous Materials trailer notified. Property Manager Paula Moshi of Colonial Apartments also requested. Due to unknown orgin of spill, Itasca Fire Department notified and responded. On ivestigation and monitioring, companies determined fuel to be diesel with green shade to it. No explosive conditions found. Apartment complex found not to be in danger.

EPA (Ed Osowski) arrived and ivestigated possible source of spill, along with Itasca water department and Roselle companies. Upon extensive investigation, found furthest sign of fuel in sewer line just south of Thorndale Av. & Hilltop intersection. This area is in the Itasca Fire Department jurisdiction. EPA and Itasca Fire Dept. investigated sewers and buildings in area, with no findings on source of spill.

Area secured and scene turned over to EPA. EPA advised a crew would be out following day to clean up fuel spill and further investigate. Companies returned in service. Paula Moshi advised of findings and of future operations from the EPA.

EPA - Edward Osowski 847.344.2431 Colonial Village - Paula Moshi 630.894.1010

* Wind direction - 6 mph out of southeast

APPARATUS				
Unit	521	Unit	541	
Type:	Engine	Type:	Rescue unit	

Use:	Suppression
Response Mode:	()
# of People	3
Injury Or Onset	//::
Alarm	10/18/2008 12:23:00
Dispatched	10/18/2008 12:25:00
Enroute	10/18/2008 12:25:00
Arrived	10/18/2008 12:29:00
Cancelled	//::
Cleared Scene	10/18/2008 17:05:00
In Quarters	//::
In Service	//::
Unit	532
Type:	ALS unit
Use:	EMS
Response Mode:	()
# of People	2
Injury Or Onset	//::
Alarm	10/18/2008 12:23:00
Dispatched	10/18/2008 12:25:00
Enroute	10/18/2008 12:25:00
Arrived	10/18/2008 12:29:00
Cancelled	//::
Cleared Scene	10/18/2008 16:09:00
In Quarters	//::
In Service	//::
Unit	MO1
Туре:	Other apparatus/resource
Use:	Suppression
Response Mode:	()
# of People	2
Injury Or Onset	//::
Alarm	10/18/2008 12:23:00
Dispatched	10/18/2008 13:20:00
Enroute	10/18/2008 13:31:00
Arrived	10/18/2008 13:45:00
Cancelled	//::
Cleared Scene	10/18/2008 16:30:00
In Quarters	//::
In Service	-/-/:
Number Of People not o	on apparatus: 6

Use:	Suppression
Response Mode:	()
# of People	2
Injury Or Onset	//::
Alarm	10/18/2008 12:23:00
Dispatched	10/18/2008 12:25:00
Enroute	10/18/2008 12:25:00
Arrived	10/18/2008 12:29:00
Cancelled	//::
Cleared Scene	10/18/2008 17:05:00
In Quarters	//::
In Service	//::
Unit	552
Туре:	Mobile command post
Use:	Suppression
Response Mode:	0
# of People	1
Injury Or Onset	//::
Alarm	10/18/2008 12:23:00
Dispatched	10/18/2008 12:52:00
Enroute	10/18/2008 12:52:00
Arrived	10/18/2008 13:08:00
Cancelled	//::
Cleared Scene	10/18/2008 17:05:00
In Quarters	//::
In Service	//::

PERSONNEL ON CALL		
Name	Personnel Rank	Apparatus
Allen, Brian	Firefighter	Other
Baker, Ron	Firefighter	521
Bieneman, Rich	Firefighter	521
Cimorelli, Charles	Firefighter/Paramedic	Other
Coppock, Matthew	Firefighter	541
Felber, Nick	Firefighter/Paramedic	532
Gnadt, David	Shift Commander	521
Howell, Chris	Shift Commander	Other
Metoyer, Andre	Deputy Chief	552
Petges, Steve	Firefighter	Other

Savoia, Nicholas	Firefighter	Other
Sielig, Adam	Firefighter	Other
Slayton, Thomas	Firefighter/Paramedic	532
Thomas, Glen	Firefighter	541